

STAT 514 Homework 10

Due: Nov 30

1. An engineer is interested in the effects of cutting speed (A), tool geometry (B), and cutting angle (C) on the life (in hours) of a machine tool. Two levels of each factor are chosen, and three replicates of a 2^3 factorial design are run. The results follow:

factor			replicate		
A	B	C	I	II	III
-	-	-	22	31	25
+	-	-	32	43	29
-	+	-	35	34	50
+	+	-	55	47	46
-	-	+	44	45	38
+	-	+	40	37	36
-	+	+	60	50	54
+	+	+	39	41	47

- (a) Estimate the factorial effects (calculate at least one main effect and one interaction by hand). Which effects appear to be large (significant)?
- (b) Use analysis of variance to confirm your conclusions for part a).
- (c) Write down a regression model for predicting tool life (in hours) based on the results of this experiment. (The model should only use significant main and interaction effects)
- (d) Analyze the residuals. Are there any obvious problems?
- (e) Generate main effect and interaction plots for significant effects. Based on them, what levels of A, B and C would you recommend?
- (f) (Optional) Generate the contour plot of the regression model. Does it provide information regarding the desirable operating conditions for the machine tool?
- (g) What is the standard error of the factorial effects?
2. An article in *Solid State Technology* describes the application of factorial designs in developing a nitride etch process on a single-wafer plasma etcher. The process uses C_2F_6 as the reactant gas. Four factors are of interests: anode-cathode gap (A), pressure in the reactor chamber (B), C_2F_6 gas flow (C), and power applied to the cathode (D). The response variable of interest is the etch rate for silicon nitride. A single replicate of a 2^4 design is run, and the data are shown below:

factor				etch rate
A	B	C	D	
-	-	-	-	550
+	-	-	-	669
-	+	-	-	604
+	+	-	-	650
-	-	+	-	633
+	-	+	-	642
-	+	+	-	601
+	+	+	-	635
-	-	-	+	1037
+	-	-	+	749
-	+	-	+	1052
+	+	-	+	868
-	-	+	+	1075
+	-	+	+	860
-	+	+	+	1063
+	+	+	+	729

Template SAS code used for the class example is in the file “design2level.sas”.

- Estimate the factorial effects. Use QQ plot to identify potentially significant effects.
- Conduct an analysis of variance to confirm your findings in a).
- What should be the appropriate regression model relating etch rate to the significant process variables?
- Analyze the residuals from this experiment. Comment on the model adequacy.
- If not all factors are important, project the 2^4 design into a 2^k design with $k < 4$ and conduct the analysis of variance.
- (Optional) Draw graphs to interpret the significant interactions.
- (Optional) Construct contour plots of the etch rate using the model in c).
- (Optional) Suppose that it was necessary to operate this process at an etch rate of 800, what settings of the process variables would you recommend?