

FIGURE 2.10 Pareto Diagram





FIGURE 2.11 Pareto Diagram for Hornpad Assembly Defects by Type



IGURE 2.6 The Basic Flowchart Symbols




FIGURE 2.3 Current Parts Order Process




FIGURE 2.4 Ideal Order Process




FIGURE 2.13 General Form of a Cause and Effect Diagram (Fishbone Diagram)




FIGURE 2.14 Cause and Effect Diagram for Factors Affecting the Ball Not Rolling in Assembled Deodorant Bottles